



Vicon Industries Inc.

Sales Alert - ViconNet IP Camera Patch 5.18

INSIDE THIS ISSUE:

5.18 Patch **Page 1**

What is in it? **Page 1**

Where to get it? **Page 1**

Written by Guy Arazi
Digital Products Manager

ViconNet IP Cameras Patch

The 5.18 software patch for the ViconNet IP cameras meant for ViconNet version 3.x based systems is part of the ongoing effort to increase performance and maintain the highest reliability possible. This patch contains several fixes to reported issues and also corrects problems related to daylight saving settings around the world.

Installation will be done using VNSetup and is described in any IP camera manual.

The patch is for the following devices running in ViconNet 3.x based systems and is **not relevant** for IP cameras running in ViconNet 2.18x based systems:

- VN-301T, VN-755IP camera, SVFT IP boards, V910 IP cameras.

Cameras running version 3.x software will show IP version **5.1x** (where **x** is any number).

- This patch isn't a MUST INSTALL patch, however Vicon always recommends to use the latest software version when possible.

What is in the 5.18 Patch ?

The following issues have been resolved and enhanced in this version:

- Time zone changes around the world to match Windows updated list
- Solve remote macro IP bug that would cause remote macro to fail
- Correct SVFT alarm input issue that would require a restart after macro setup
- Enhance logging functions for technical support purpose

Where to get it ?

The 5.18 software version will be added to the ViconNet 3.2c CD and replace the existing version 5.17. The version will be put into production and loaded on all the new production IP boards.

Vicon will also publish a copy of this version on the Vicon FTP site, which can be reached through the following links:

3.2 CD, including patch: http://ftp.vicon-cctv.com/Software/01_Dig_Video/VNET/
IP Camera update only: http://ftp.vicon-cctv.com/Software/01_Dig_Video/IPCAM/